

Release Note DS-AC1 v1.0.0.14

New Features

N/A

Issues Fixed & Modification

v1.0.0.14

- Modified HID behavior so that the cursor automatically hides after being idle for 2 seconds.
- Fixed "The home page in the online controller was covered by a gray overlay whenever there was a change in the volume meter."
- Fixed "The online controller page was covered by a gray overlay after closing the information window."
- Fixed "IR command learning failed when the command code contained '0x00'."
- Modified the system so that commands cannot use the same name to avoid confusion and errors.
- Added device names for each of the RS-232/RS-485/TCP control interfaces.
- Added support for exporting and importing command lists.
- Added a return-to-admin button on the online controller web page.
- Modified the GUI default page to the device control page.
- Modified the default username and password for the device control page.
- Modified the menu sidebar style (Hidden/Refresh button).
- Fixed "A long device description could cause its text to exceed the GUI message box."
- Fixed "The layout of the date and time selection menus was not aligned when manually setting the date and time."
- Fixed "The browser didn't redirect to the web interface after applying a fixed IP."
- Fixed "Changes made to a scheduled event were not applied; DS-AC1 still did control based on the old configuration."

Limitation & Known Issue

- The video indication of firmware update appears more than 1 minute after the update starts.
- IR I/O now only supports the NEC protocol.
- Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.