Release Note LS-410 v1.0.0.32

New Features

N/A

Issue Fixed & Modification

V1.0.0.32

- Modified the register key of ARECloud into concealed text.
- Fixed "Editing layouts in the theme editor could create layouts that cause the system to crash".
- Fixed "RS-232/TCP commands for display port layout switching did not work".
- Fixed "The wed page got stuck in the loading process after enabling/disabling NDI streaming".
- Fixed "Constantly switching between the web admin and online director page during a live stream could eventually crash the streaming function".
- Fixed "Formatting a USB drive could not be completed".
- Hard fix for "When scheduling recordings using Kaltura, Stations did not start and stop recording according to the event times".
  This issue was found in early April 2024 and was fixed in Kaltura SaaS version Tucana-20.11.0, tested on May 20th, 2024.

- Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.