


Release Note DS-4CU **VA1** v6.1.10.13



(This version is only compatible with the new HW version – VA1)

Device Hardware Version

1. Please find your device serial number (S/N), it can be found either on the label or on the web Administration page.



2. Check the 10th digit of the S/N. If it is “V”, then the device has the new hardware. If it is “0”, it has the original hardware and is not compatible with the firmware series described in this release note.



New Features

Added support of “Audio-Technica ATND1061”

Support List:

- Shure DDS 5900
- Show DCS-100M
- Bosch CCS 1000D
- HAYACO WMC 240G
- Sennheiser ADN CU1
- Televic Plixus AE-R
- Audio-Technica ATUC-50CU
- Televic D-Cerno
- Shure MXA 310/710/910
- Shure MXW
- Shure MXCW
- Bosch Dicontis Wireless system
- Televic Confidea FLEX G4 wireless
- BXB FCS-6350
- Audio-Technica ATND1061

Issue Fixed & Modification

- The maximum amount of overlay that can be added has been increased to 256.
 - Supports Audio-Technica ATND1061 microphone system in mode leveraging camera tracking ID from ATND.
 - Add a toggle button to enable or disable speaker tracking.
 - Supports Audio-Technica ATND1061 microphone system in 8-sector mode.
 - Fix “The inability to receive multicast packages under certain network environments.”
 - Fix “Televic Confidea Wireless G4 microphone status was not synchronized after system reboot.”
 - Fix “DS-4CU sent different commands than defined in external device control function.”
-
- **Notice: During the firmware update progress, please always keep the power on to prevent permanent system unstable or damage.**